

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
Emigrant Landing Entrance Area	Boat inspection station	1	Good	
	Entrance kiosk	1	Good	
	Entrance station	1	Good	
	Signs	7	Good to excellent	6 signs are informational and 1 are directional
Emigrant Landing Boat Launch	Restroom	1	Good	Unisex, ADA, flush toilets
	Admin Building	1	Good	
	Above Gas Storage	1	Good	
	Bench	1	Good	
	Drinking fountains	2	Excellent	2 drinking fountains
	Boat Dock with boat ramp	1	Excellent	Boat dock and ramp for public use
	Boat Dock	1	Excellent	Boat dock for law enforcement use
	Signs	16	Fair to good	14 signs are information signs and 2 are directional.
Emigrant Landing Picnic and Fishing Area One	Restroom	1	Good	
	Restroom	1	Good	
	Drinking fountains	1	Good	
	Trash receptacles	6	Excellent	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
	Picnic sites	21	Good to Excellent.	1 picnic site is considered to be in poor condition due to the shade structure missing
	Pyramid Lake treatment	1	Good	
	Fish washing station	1	Good	
Emigrant Landing Picnic and Fishing Area Two	Restroom	1	Good	
	Building	1	Good	
	Boat Dock	1	Poor	Dock is disconnected and would need repair.
	Drinking fountains	3	Poor	2 out of the 3 faucets are considered to be in poor condition. There is no functioning water. The remaining faucet is considered to be in excellent condition.
	Water spigots	1	Fair	Leaking spigot
	Picnic sites	6	Excellent	
	Shade structures	1	Excellent	3 shade structures are combined to 1
	Standard tables	14	Excellent	
	Grills	7	Excellent	
	Trash receptacles	3	Good to Excellent	
Signs	24	Good to Excellent	Of the 24 signs 2 signs are in poor condition; 1) the sign is missing, and wood is split; 2) the sign is faded and bent.	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
				17 signs are informational and 7 are directional
Emigrant Landing Swim and Picnic Area	Restroom	1	Fair	
	Restroom	1	Fair	
	Lifeguard tower	1	Poor	
	Water spigots	5	Excellent	1 water spigot is in fair condition. The water spigot is leaking.
	Drinking fountains	2	Good	
	Trash receptacles	7	Good to excellent	
	Picnic sites	31	Good	
	Shade structures	31	Good	
	Standard tables	52	Good	
	Accessible tables	8	Good	
	Grills	34	Good	
	Signs	13	Good to excellent	Of the 13 signs 1 sign was in poor condition. information and directional signs All signs are informational
Vista del Lago Visitor Center	Visitor center building	1	Excellent	
	Entrance station	1	Good	
	Look out	1	Excellent	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
	Trash receptacles	11	Fair to Good	
	Telescope viewers	2	Excellent	
	Lights	8	Excellent	
	Signs	3	Good	1 FERC sign and 2 informational signs
Vaquero Day Use Area	Restroom	1	Good	
	Restroom	1	Excellent	
	Lifeguard tower	1	Fair	
	Boat ramp	1	Excellent	2 lane boat ramp
	Picnic sites	14	Good to excellent.	1 accessible/ada site Some concrete pads have slight cracking.
	Grills	14	Good	
	Standard tables	13	Good	
	ADA tables	1	Good	
	Trash receptacles	5	Good	
	Water spigots	5	Good	
	Drinking fountain	1	Good	
	Fire pit	1	Good	BBQ style pit
Signs	14	Fair to good	1 sign is in poor condition, it is illegible.	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
				13 signs are informational and 1 is directional
Spanish Point Boat-in Picnic Area	Restroom	1	Good	Pit toilets
	Ski Launch	1	Poor	
	Picnic Sites	9	Good	
	Shade structures	3	Good	
	Grill	12	Good	1 grill has 3 grills combined
	Standard tables	32	Good	
	Trash receptacles	5	Good	Double bear proof receptacle
	Signs	1	Good	1 sign is informational
Serrano Boat-in Picnic Area	Restroom	1	Good	
	Picnic sites	6	Good	
	Trash receptacles	2	Good	Double bear proof receptacle
	Standard tables	12	Good	
	Boat Dock	1	Good	
	Grills	6	Good	
Bear Trap Boat-in Picnic Area	Picnic sites	2	Good	
	Shade structure	1	Good	
	Standard tables	2	Good	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
	Grills	2	Good	
	Trash receptacles	2	Good	Double and single bear proof
	Restroom	2	Good	
	Signs	1	Excellent	1 sign is informational
Yellow Bar Boat-in Picnic Area	Restroom	2	Excellent	
	Boat Dock	1	Good	
	Shade structures	10	Good	1 shade structure is in fair condition. The structure is chipping and has worn out supports.
	Accessible tables	3	Good	
	Standard tables	17	Good	
	Trash receptacles	2	Good	
	Sign	1		1 sign is informational. "Yellow Bar" sign nailed into a shaded structure
Quail Lake Day Use Area	Restroom	1	Good	Portable restroom
	Signs	3	Good to Excellent	2 signs are informational and 1 sign is directional
Los Alamos Group Campground	Restroom	1	Good	
	Campsites	3	Good	
	Shade structures	3	Good	
	Water spigots	3	Excellent	1 Water spigot is in poor condition. The spigot is leaking
	Sinks	1	Good	

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
	Trash receptacles	3	Good	
	Standard tables	15	Good	
	Campfire	3	Good	
	Grills	3	Good	
	Signs	5	Good to excellent	
Los Alamos Campground	Restroom	1	Good	flush toilets
	Restroom	1	Good	flush toilets
	Restroom	1	Good	flush toilets
	Restroom	1	Good	flush toilets
	Campsites	93		<p>typically, 1 picnic table and 1 fire ring per site. 5 portable ramadas that are deployed to campsites as needed</p> <p>Campsites in poor condition: Loop 2 site 26: add more gravel to parking spur, fix leaking, fix erosion, fix parking barrier 4 ADA campsites: Loop 3 Site 49: Parking is accessible but no accessible route to the amenities. Replace site number support. Replace table with ADA compliant table. Loop 3 Site 48: Parking 12x 18 feet. driveway slope is 5%, 4.6% cross slope, parking stall 1.3%, .7 % cross slope. No accessible point of travel from parking to campsite amenities. Site marker has fallen over, make ADA accessible throughout campsite Loop 2 site 21: cross Slope .5, .2 slope, 2.2 slope for driveway. Campsite is not ADA accessible from parking area to other campsite amenities. Only parking spot is ADA compliant</p>

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
				Loop 1 Site 5: Driveway 43x13. Cross slope 4.7. Slope 1.6. Parking Cross slope 1.6. Slope 1.6. Driveway is too steep. ADA table. No access from parking to other campsite amenities.
	Water spigots	31	Good to Excellent	2 spigots are in poor condition. They are both cracked an have no water accessibility.
	Sinks	4	Good	
	Standard tables	93	Good	
	Grills	93	Good	
	Trash receptacles	16	Good	
	Dump stations	2	Good	Dump station spigot is not working.
	Pay tube	1	Good	
	Horseshoe pit	1	Poor	Horseshoe pit is not clearly marked
	Volleyball court	1	Good	Sand is hard, and weeds are growing.
	Signs	23	Fair to Excellent	13 signs are informational and 10 are directional

Recreation Facility	Recreation Amenities	Quantity	2018 Condition Summary	Notes
Frenchman's Flat (non-Project facility maintained by USFS)	Restroom	1	Excellent	Pit toilets. 2 stalls
	Restroom	1	Poor	Pit toilets. 1 stall, broken window panes and broken door.
	Standard tables	3	Fair	
	Trash receptacles	6	Good to excellent	3 dumpsters are in poor condition. Missing hatches and what appears to be bullet holes throughout the face.
	Campsite	3	Fair	
	Signs	7		All 7 signs are informational