

**Riparian Unit and Shoreline Assessment Data Form**

Shoreline/ Riparian Unit ID: QR-6 Date: 5/3/17  
 Coordinates- Start: Obtain from GIS Coordinates- End: \_\_\_\_\_ Surveyor(s): RB, MG, LF  
 Unit Length: \_\_\_\_\_ Assessment Method: Visual inspection  
 Reaches within Unit: \_\_\_\_\_  
 Additional Features within Unit: \_\_\_\_\_

**VEGETATION**

Community Type (Source): Rip-rap - barren sparse vegetation, scrub

| Dominant Over-Story (Species/% Cover) | Dom. Mid-Strata (Species/% Cover) | Dom. Under-Story (Species/% Cover) |
|---------------------------------------|-----------------------------------|------------------------------------|
| —                                     | Rabbit brush - 2%                 | —                                  |
|                                       |                                   |                                    |
|                                       |                                   |                                    |
|                                       |                                   |                                    |
|                                       |                                   |                                    |

**HYDROLOGY**

Description of Hydrologic Regime: Rip-rap shoreline

**LANDSCAPE**

Description of geomorphic regime (erosion processes, upland condition, substrate, etc): ≥45° rip-rap slope from water's edge to roadway. Hill slopes up from roadway

**OTHER INFORMATION**

Unit Assessment Rational: Contiguous rip-rap bank w/ little to no veg.

Additional Notes: \_\_\_\_\_